Report Date Range: 01/10/2026 to 31/10/2026

This report shows the number of safety defects (split by defect type and location) completed by Somerset Highways within your division for the previous month.

For reference, codes starting with T or U represent Unclassified roads.

Blackmoor Vale ED

• **CW- Carriageway Pothole**	A30/710	SHERBORNE ROAD	5
• **CW- Carriageway Pothole**	T5801/30	CORTON DENHAM ROAD - CORTON DENHAM	2
• **CW- Flooding in Carriageway**	T5825/20	STATION ROAD	2
• **CW- Step in Level**	A30/710	SHERBORNE ROAD	1
• **TR - Tree Down on Highway**	A30/820	SHERBORNE ROAD - HENSTRIDGE	1
• **Bollard Damaged**	A357/110	STALBRIDGE ROAD / HIGH STREET / ASH WALK - HENSTRIDGE	1
• **CW- Carriageway Pothole**	B3145/130	SHERBORNE ROAD - CHARLTON HORETHORNE	1
• **TR - Tree Down on Highway**	B3145/160	CHARN HILL / CHARLTON HILL - CHARLTON HORETHORNE	1
• **FW- Footway Pothole**	F1084/110	URBAN FOOTPATH	1
• **Multiple CW Safety Defects**	T5801/20	MIDDLE RIDGE LANE - CORTON DENHAM	1
• **CW- Carriageway Pothole**	T5801/20	MIDDLE RIDGE LANE - CORTON DENHAM	1
• **TR - Tree Down on Highway**	T5843/60	QUARRY HILL - COMPTON PAUNCEFOOT	1
• **TR - Tree Down on Highway**	T5898/30	MAPERTON ROAD - MAPERTON	1
• **FW- Step in Level: Other**	U5823/10	GAINSBOROUGH	1
• **CW- Carriageway Pothole**	U5827/70	WHEATHILL LANE	1
• **Multiple CW Safety Defects**	U5827/70	WHEATHILL LANE	1
• **GY- Blocked Drainage System**	U5827/70	WHEATHILL LANE	1
• **CW- Step in Level**	U5836/15	HORSE LANE - CHARLTON HORETHORNE	1
• **CW- Carriageway Pothole**	U5845/20	GOATHILL LANE - SOUTH CHERITON	1
• **TR - Tree Down on Highway**	U5848/11	HORSINGTON ROAD - HORSINGTON	1
• **CW- Carriageway Pothole**	U5910/10	COMMON LANE - YENSTON	1
• **Multiple CW Safety Defects**	U5910/10	COMMON LANE - YENSTON	1
• **CW- Carriageway Pothole**	U5917/35	LILY LANE	1
• **CW- Step in Level**	U8657/10	HOLTON STREET - HOLTON	1

Total: **33**